

Terraprobe -- 3-19-0028-02  
 Blue Fairway Blocks 5 & 6, Collingwood

Additional groundwater measurements provided August 14th by Terraprobe

Monitoring/ Borehole Location	Ground Surface Elevation (m)	Static Water Level Depth Below Existing Ground Surface (m)									
		23-May-19	29-May-19	13-Jun-19	10-Jul-19						
BH1	184.2	-1.5	-0.9	-1.2	-1.5						
BH3	184.8	-0.6	-0.4	-0.7	-1.2						
BH9	185.7	-0.8	-0.8	-0.8	-1.1						
BH11	186.9	-1.0	-1.1	-1.2	-1.5						

noted

Monitoring/ Borehole Location	Ground Surface Elevation (m)	Static Water Level Elevation (m)									
		23-May-19	29-May-19	13-Jun-19	10-Jul-19						
BH1	184.2	182.7	183.3	183.0	182.7						
BH3	184.8	184.2	184.4	184.1	183.6						
BH9	185.7	184.9	184.9	184.9	184.6						
BH11	186.9	185.9	185.8	185.7	185.5						

noted